B.R No . 892\14-15 Date:31.01.2015

Improvements to Drain, foot path 1st 2nd 3rd 4th 5th cross (Brundavna layout) Mallasandra in Bagalgunte ward no14

QUALITY CONTROL

BR No : 892/14-15, 31.08.2015

NAME OF THE WORK: Improvements to Drain, foot path 1st 2nd 3rd 4th 5th cross (Brundavna layout) Mallasandra in Bagalgunte ward no14

On verification of quality control test reports available in the file and also from inspection report of technical team Deployed for this purpose generally the work executd is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed Years back.

Asst.Executive Engineer
T.Dasarahalli Sub Division
BBMP, Bangalore

Executive Engineer
Dasarahalli Division
BBMP, Bangalore

Name of Work:	Improvements to Drain, foot path 1st 2nd 3rd 4th 5th cross (Brundavna layout) Mallasandra in Bagalgunte ward no14
B.R.No	892\14\15
Estimated Cost	20
Bill Amount Rs.	18.35695
Date of Inspection	05-03-2016

Observation and Conclusion

The above said work Improvements to Drain, foot path 1st 2nd 3rd 4th & 5th Cross (Brundavan layout) Mallasandra in Bangalore ward no 14 was shown to me by the Concerned A.E.

The above said work was inspected by me along with the Concerned AE Shri Manjunath.

The measurements at Selected Stretches were verified and found Satisfactory

The work done is satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements to Drain, foot path 1st 2nd 3rd 4th 5th cross (Brundavna layout) Mallasandra in Bagalgunte ward no14

BR No. 892/14-15, Date.31.01.2015



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of work:- Improvements to Drain foot path Rd and 3rd, 4th & 5th Cross Brundavana Layout Mollasandra in Bagalagunte W.No.14.



Encl:

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT